



1/27

Fig. 1
(Prior Art)




2/27

Fig. 2




3/27



Fig. 3

4/27



Fig. 4




5/27

Fig. 5**Fig. 6**


6/27

Fig. 7**Fig. 8**

7/27


Fig. 9

8/27

Fig. 10

9/27

Fig. 11



10/27

Fig. 12







Fig. 13




11/27


Fig. 14**Fig. 15**

12/27



Fig. 16




13/27

Fig. 17


14/27

Fig. 18**Fig. 19**

15/27

Fig. 20

16/27

Fig. 21

18/27

Fig. 24

Sub-section code		Sub-section name	Alarm table
110	Outer blocks	Outer blocks	1
200	Restaurants	Dining Area	1
240	Kitchens	Kitchens	1
300	Halls	Halls	2
400	Building maintenance	Building maintenance facilities	2
500	Supplementary facilities	Supplementary facilities	2
600	Business attachments	Business attachments	2
601	Business attachments	Food stores	2
602	Business attachments	Shops	2
701	Medical facilities	Clinics	3
702	Medical facilities	Wards	2
703	Medical facilities	Emergency rooms	3
704	Medical facilities	Mortuaries	2
705	Medical facilities	Examination rooms	3
800	Production lines	Production lines(overall)	2
901	Common space	Offices	3
902	Common space	Lavatories	1
903	Common space	VIP rooms	3
904	Common space	Guest rooms	3
905	Common space	VIP rooms	3
906	Common space	General wards	3
907	Common space	Vending machines	3
908	Common space	Dormitory	2
909	Common space	Lodge	2
910	Common space	Shade houses	2
911	Common space	Pantries	2
912	Common space	Lobby	2
999	Etc.	Etc.	2

Fig. 25

[DD/MM/YYYY] Pest-related information report

Number of pest in activity per each building [Period 1]

Pest	Outer blocks			Warehouse		Production building			
	Location1	Location2	Location3	Location1	Location2	Production Dept.	Storage Dept.	Aging Dept.	Lavatory
Cockroaches									

Number of pest in activity per each building [Period 2]

Pest	Outer blocks			Warehouse		Production building			
	Location1	Location2	Location3	Location1	Location2	Production Dept.	Storage Dept.	Aging Dept.	Lavatory
Cockroaches									

Number of pest in activity per each building [Period 3]

Pest	Outer blocks			Warehouse		Production building			
	Location1	Location2	Location3	Location1	Location2	Production Dept.	Storage Dept.	Aging Dept.	Lavatory
Cockroaches									


•
•
•

20/27


Fig. 26

	Large section	Production building	Description of location			
No.	Floor/Middle section	Sub-section		Sub-section code	Name and quantity of install equipment	Vulnerable section
	B1/Office	Customer center				
	/	Education room				
	/Warehouse	ACS warehouse				
	/	Document warehouse				
	Lobby	Lobby				
	/	Lavatory				
	1st floor/ Production line 1	Production Dept.	Next to elevator	200	A-2/3	
	/	Storage Dept.	Next to Lavatory	200	A-2/2	
	/	Aging Dept.	Opposite to elevator	603	C-2/4	
	/	Lavatory	Left of staircase	912	C-1/4	
	Rooftop/Rooftop	Rooftop				
	/	Animal breeding room				


21/27

Fig. 27


22/27

Fig. 28


23/27

Fig. 29


24/27

Fig. 30

25/27

Fig. 31

26/27

Fig. 32

27/27

Fig. 33